

PUNTAS DE ATORNILLADOR

PUNTAS PHILLIPS



Referencia	⊕	↔
1001	1	25
1002	2	25
1003	3	25



Referencia	⊕	↔
1012	2	25



Referencia	⊕	↔
1061	1	50
1062	2	50
1063	3	50
1071	1	70
1072	2	70
1082	2	90

PUNTAS PHILLIPS DOBLES



Referencia	⊕	↔
413031	1	65
413042	2	65

PUNTAS POZIDRIV



Referencia	⊕	↔
1001PZ	1	25
1002PZ	2	25
1003PZ	3	25



Referencia	⊕	↔
1061PZ	1	50
1062PZ	2	50
1063PZ	3	50

EXTENSIONES



Referencia	○	↔
5002	1/4"	50
5003	1/4"	75
5012	3/8"	50
5013	3/8"	75

PUNTAS TORX



Referencia	⊗	↔
T6	6	25
T7	7	25
T8	8	25
T9	9	25
T10	10	25
T15	15	25
T20	20	25
T25	25	25
T27	27	25
T30	30	25
T40	40	25



Referencia	⊗	↔
T107	7	50
T109	9	50
T110	10	50
T115	15	50
T120	20	50
T125	25	50
T127	27	50
T130	30	50
T140	40	50

PUNTAS TORX INVIOLABLE



Referencia	⊗	↔
T7H	7	25
T8H	8	25
T9H	9	25
T10H	10	25
T15H	15	25
T20H	20	25
T25H	25	25
T27H	27	25
T30H	30	25
T40H	40	25

ADAPTADORES



Referencia	○	↔
BH-421M	Magnético	60
BH-423M	Magnético	75

PUNTAS ALLEN



Referencia	○	↔
21025	2,5	25
21003	3	25
21004	4	25
21005	5	25
21006	6	25
21008	8	25



Referencia	○	↔
21225	2,5	50
21203	3	50
21204	4	50
21205	5	50
21206	6	50

PUNTAS PLANAS



Referencia	⊖	⊕	↔
1501	5	0,8	25
1502	5,5	1	25
1503	6	1	25
1504	7	1,2	25
1505	8	1,2	25



Referencia	⊖	⊕	↔
1521	5	0,8	50
1524	6	1	50
1525	7	1	50

PUNTAS PLANAS CON CASQUILLO GUIA



Referencia	⊖	⊕	↔
6001	5	0,91	95
6002	5,5	0,97	95
6003	7	1,17	95
6004	10	1,4	95